




ME-109 SHEET TWO

The Messerschmitt had its vices: the cockpit was small, the heavily framed canopy restricted the pilot's field of view and the plane's narrow undercarriage made it extremely prone to ground accidents. Many of the 33,000 Me-109s produced were lost in ground accidents.




PROPELLER


WING SCOOPS




TAIL STRUTS




LANDING GEAR



WHEELS TO BE ADDED TO THE L.G



BLISTERS



WING CROSS SECTION

SCORE, BEND & GLUE (LOWER WING SURFACE)

LH WING SCOOPS

RH WING SCOOPS

BLISTER

BLISTER

DIHEDRAL REFERENCE

GLUE AREA

GLUE AREA

SCORE, BEND & GLUE